



Dia. for Galv. steel, blue passiv. Art. No. in mm in mm in mm screw 10 3.2 0.80 04113 10 M 3 20 3.6 1.25 04113 100/500/1000 12 1.25 4.3 04114 12 M 4 20 4.3 1.25 04114 100/300/1000 20 15 5.3 1.25 04115 100/500/1000 20 5.3 1.25 04115 20 100/250/500/1000 M 5 25 1.25 04115 5.3 25 100/300/1000 30 5.3 1.25 04115 30 15 1.50 04116 6.4 15 100/500/1000 18 1.50 6.4 04116 18 100/250/500/1000 20 6.5 1.25 04116 20 20 04116 2.00 202 100/300 6.5 M 6 25 6.5 1.25 04116 100/300/500/1000 25 30 1.25 6.5 04116 100/300/500 2.00 30 6.5 04116 302 100/300 40 6.5 1.50 04116 40 40 6.5 3.00 04116 403 20 1.25 100 7.5 04117 20 M 7 25 1.25 04117 20 8.5 1.25 04118 20 100/300/500/1000 25 8.5 1.25 04118 24 25 8.5 3.00 04118 243 100/300 100/300/1000 M 8 25 8.5 1.50 04118 25 25 2.00 100/500 8.5 04118 252 30 8.5 1.50 04118 2.00 8.2 40 100/300 04118 40 40 8.4 3.00 04118 403 20 10.5 1.50 041110 20 24 10.5 4.00 041110 24 100/500 25 10.5 1.50 041110 25 M10 30 10.5 1.50 041110 30 3.00 10.5 041110 303 30 10.5 4.00 041110 304 40 10.2 2.00 041110 40 100/300 32 13.0 1.50 041112 30 40 13.0 2.00 041112 40 M12 100 40 13.0 4.00 041112 404 2.50 50 13.0 041112 50 30 1.50 50/100 15.0 0411 14 30 40 15.2 2.00 041114 40 M14 40 4.00 041114 404 50

| Dia. for screw | d ₁ in mm | d in mm | h in mm | Galv. steel, yellow pass. Art. No. | P. Qty. |
|-------------------|-------------------------|------------|------------|---|-------------|
| M 5 | 20 | 5.3 | 1.25 | 0411 05 20 | |
| M 6 | 20 | 6.5 | 1.25 | 0411 06 20 | 100/300/500 |
| M 8 | 24 | 8.5 | 1.25 | 0411 08 24 | |
| M 10 | 30 | 10.5 | 1.50 | 0411 010 30 | 100/500 |

041114

041114

041116 40

041116 50

041116 504

45

50

50/100

2.00

2.50

2.00

2.00

4.00

15.0

15.0

15.0

16.2

17.0

17.0

45

50

40

50

50

Wing Repair Washers

According to DIN 522, medium

Galvanised steel, blue passivated

Assortment



Contents: 16 Dimensions from 4×12 to $12 \times 30 = 1400$ pieces.

Art. No. 0964 411

Galv. steel, yellow passivated

M16