

Fix Cable Connectors

- For branch connections at any desired location.
- For mechanically permanent, shockproof, electrically proper, long-lasting connections.
- Extremely easy to install, as no special tools are required.

Areas of application: Motor vehicle electrical systems, switchgear construction, measuring and control engineering.

| ORSY | Connection principle | Cable cross section in mm ² | max. voltage in V | max. temperature in °C | Art. No. | P. Qty. |
|------|----------------------|--|-------------------------|------------------------------|------------|---------|
| | | 0.5 – 1.5 | 400 | 105 | 0555 557 | |
| 1 | | 1.0 – 2.5 | | | 0555 564 | |
| 1 | | 4.0-6.0 | | | 0555 562 | 50/100 |
| | | Continuity 4.0 Branch 1.5 | | | 0555 562 1 | |
| | | 0.75 – 2.5 | | | 0555 564 1 | |

Branch connector, non-detachable



Lay wires in Fix cable connector. Caution: Do not strip wire!



Produce connection with common combination pliers.



Close locking tab.



Finished!

| ORSY | Connection principle | Cable cross section in mm ² | max. voltage in V | max. temperature in °C | Art. No. | P. Qty. |
|--|----------------------|--|-------------------------|------------------------------|------------|---------|
| The state of the s | | 0.5 – 0.75 | 300 | 105 | 0555 951 | 50/100 |
| - | | 0.5 – 1.5 | | | 0555 951 1 | |
| - | | 0.75 – 2.5 | | | 0555 952 | |
| 0 | | 1.5 – 2.5 | | | 0555 952 1 | |
| | | 4.0 | | | 0555 953 | |
| 10 | | 4.0-6.0 | | | 0555 953 1 | |

Branch connector, detachable



Lay wire in Fix cable connector. Caution: Do not strip wire!



Produce connection by closing Fix cable connector.



Insert fully insulated pushon tab with crimped wire in Fix cable connector.



Finished!