




**ORSY**


## Wing Nuts similar to DIN 315 American shape

Galvanized steel, A2,A4  
blue passivated (sim. to DIN)

Thr. dia. d in mm	d <sub>1</sub> in mm	e in mm	h in mm	g in mm	Steel galv., blue pass. Art. No.	P. Qty.	A2 simil. DIN 314 Art. No.	P. Qty.	A4 simil. DIN 314 Art. No.	P. Qty.
M3	6	12.6	6.4	1.1	<b>0342 3</b>				<b>0340 033</b>	
M4	8	17.6	8.6	1.6	<b>0342 4</b>				<b>0340 034</b>	
M5	10.3	22.5	11	2.1	<b>0342 5</b>	100			<b>0340 035</b>	
M6	12.7	27.8	13.6	2.5	<b>0342 6</b>				<b>0340 036</b>	
M8	13.8	30.3	14.8	2.8	<b>0342 8</b>				<b>0340 038</b>	
M10	16.5	36.2	17.7	3.3	<b>0342 10</b>	50	<b>0344 010</b>	10	<b>0340 031 0</b>	
M12	22.5	49.4	24.1	4.5	<b>0342 12</b>		<b>0344 012</b>	5	<b>0340 031 2</b>	
M14	28.5	59.4	31.1	5.7	<b>0342 14</b>	25			<b>0340 031 4</b>	50
M16	34.5	61	38.2	6.9	<b>0342 16</b>				<b>0340 031 6</b>	20



**ORSY**


## Wing Nuts

DIN 315  
malleable cast iron

A2   
A4

Thr. dia. d in mm	d <sub>1</sub> in mm	e in mm	h in mm	g in mm	Malleable cast iron Art. No.	P. Qty.	A2 Art. No.	P. Qty.	A4 Art. No.	P.
M4	6	18	8.5	1.9	<b>0342 04</b>		<b>0344 004</b>	100	<b>0340 044</b>	
M5	8	24	11	2.3	<b>0342 05</b>		<b>0344 005</b>		<b>0340 045</b>	100
M6	10	30	15	2.3	<b>0342 06</b>		<b>0344 006</b>		<b>0340 046</b>	
M8	13	36	18	2.8	<b>0342 08</b>		<b>0344 008</b>	50	<b>0340 048</b>	50
M10	17	48	23	4.4	<b>0342 010</b>		<b>0344 001 0</b>		<b>0340 041 0</b>	
M12	20	62	31	4.9	<b>0342 012</b>		<b>0344 001 2</b>		<b>0340 041 2</b>	
M16	26	70	35	6.4	<b>0342 016</b>	25	<b>0344 001 6</b>	20	<b>0340 041 6</b>	
M20	32	86	44	6.9	<b>0342 020</b>	10			<b>0340 042 0</b>	20


**ORSY**


## Wing Screws

DIN 316

malleable cast iron

Thr. dia. d	M4	M5	M6	M8	M10
d <sub>1</sub> in mm	6	8	10	13	17
e in mm	18	24	30	36	48
h in mm	8.5	11	15	18	23
g in mm	1.9	2.3	2.3	2.8	4.4

Thr. dia. d → Malleable cast iron in mm ↓	M4 Art. No.	P. Qty.	M5 Art. No.	P. Qty.	M6 Art. No.	P. Qty.	M8 Art. No.	P. Qty.	M10 Art. No.	P. Qty.	M12 Art. No.	P. Qty.
10			<b>0237 5 10</b>		<b>0237 6 10</b>	250	<b>0237 8 10</b>					
12			<b>0237 5 12</b>	250	<b>0237 6 12</b>	50	<b>0237 8 12</b>					
16	<b>0237 4 16</b>	250	<b>0237 5 16</b>		<b>0237 6 16</b>		<b>0237 8 16</b>		<b>0237 10 16</b>	50		
18							<b>0237 8 18</b>					
20	<b>0237 4 20</b>	250	<b>0237 5 20</b>		<b>0237 6 20</b>		<b>0237 8 20</b>		<b>0237 10 20</b>		<b>0237 12 20</b>	
25			<b>0237 5 25</b>		<b>0237 6 25</b>		<b>0237 8 25</b>		<b>0237 10 25</b>		<b>0237 12 25</b>	25
30	<b>0237 4 30</b>	250	<b>0237 5 30</b>		<b>0237 6 30</b>	50	<b>0237 8 30</b>		<b>0237 10 30</b>		<b>0237 12 30</b>	
35			<b>0237 5 35</b>		<b>0237 6 35</b>		<b>0237 8 35</b>		<b>0237 10 35</b>		<b>0237 12 40</b>	
40			<b>0237 5 40</b>		<b>0237 6 40</b>		<b>0237 8 40</b>		<b>0237 10 40</b>		<b>0237 12 50</b>	
50					<b>0237 6 50</b>	50	<b>0237 8 50</b>		<b>0237 10 50</b>		<b>0237 12 60</b>	25
60					<b>0237 6 60</b>	100			<b>0237 10 60</b>			