



Hexagon screws

with shank
according to DIN 931 (ISO 4014)

Bare steel 8.8
Galvanized steel 8.8, blue passivated
Galvanized steel 8.8, yellow passivated
Bare steel 10.9
A2

ORSY

Thr. dia. d	M 4	M 5	M 6	M 8	M 10	M 12	M 14	M 16	M 18	M 20	M 24	M 27	M 30	M 36			
b (up to 125)	in mm	14	16	18	22	26	30	34	38	42	46	54	60	66			
b (from 125)	in mm	-	22	24	28	32	36	40	40	44	52	60	66	72			
k	in mm	2.8	3.5	4	5.3	6.4	7.5	8.8	10	11.5	12.5	15	17	18.7	22.5		
Thr. dia. d	l in mm	Steel 8.8	8	P.Qty.	10	13	Steel 8.8 galv.,	22	P.Qty.	Steel 8.8 galv.,	P.Qty.	Steel 10.9	100	Rost. frei	46	Rost. frei	A2
P.Qty.	in mm	bright	Qty.	blue pass.	Qty.	yellow pass.	Qty.	bright	Qty.	Art. No.	Qty.	Art. No.	Qty.	Art. No.	Qty.	Art. No.	Qty.
		Art. No.		Art. No.		Art. No.		Art. No.									
M 4	25	0051 4 25	100	0053 4 25	100	0053 04 25	100		100		100		100		100		100
	30	0051 4 30		0053 4 30		0053 04 30											
	35	0051 4 35		0053 4 35		0053 04 35											
	40	0051 4 40		0053 4 40		0053 04 40											
	45	0051 4 45		0053 4 45		0053 04 45											
	50	0051 4 50		0053 4 50		0053 04 50											
	55	0051 4 55		0053 4 55		0053 04 55											
	60	0051 4 60		0053 4 60		0053 04 60											
	65	0051 4 65		0053 4 65		0053 04 65											
	70	0051 4 70	0053 4 70	0053 04 70													
M 5	80	0051 5 80	100	0053 4 80	100		100		100		100		100		100		100
	25	0051 5 25		0053 5 25		0053 05 25											
	30	0051 5 30		0053 5 30		0053 05 30											
	35	0051 5 35		0053 5 35		0053 05 35											
	40	0051 5 40		0053 5 40		0053 05 40											
	45	0051 5 45		0053 5 45		0053 05 45											
	50	0051 5 50		0053 5 50		0053 05 50											
	55	0051 5 55		0053 5 55		0053 05 55											
	60	0051 5 60		0053 5 60		0053 05 60											
	65	0051 5 65		0053 5 65		0053 05 65											
	70	0051 5 70		0053 5 70		0053 05 70											
	85					0053 05 85											
	90	0051 5 90		0053 5 90		0053 05 90											
	100	0051 5 100		0053 5 100													
	110	0051 5 110	0053 5 110														
	120	0051 5 120	0053 5 120														
	130	0051 5 130	0053 5 130														
M 6	140	0051 5 140	0053 5 140														
	30	0051 6 30	500	0053 6 30	100	0053 06 30	100	0052 6 30	200	0095 6 30	100	0090 6 30	50				
	35	0051 6 35	200	0053 6 35	200	0053 06 35	200	0052 6 35	200	0095 6 35	200	0090 6 35	200				
	40	0051 6 40		0053 6 40		0053 06 40		0052 6 40		0095 6 40		0090 6 40					
	45	0051 6 45	200	0053 6 45	200	0053 06 45	200	0052 6 45	200	0095 6 45	200	0090 6 45	200				
	50	0051 6 50		0053 6 50		0053 06 50		0052 6 50		0095 6 50		0090 6 50					
	55	0051 6 55		0053 6 55		0053 06 55		0052 6 55		0095 6 55		0090 6 55					
	60	0051 6 60	100	0053 6 60	100	0053 06 60	100	0052 6 60	100	0095 6 60	100	0090 6 60	100				
	65	0051 6 65		0053 6 65		0053 06 65		0052 6 65		0095 6 65		0090 6 65					
	70	0051 6 70		0053 6 70		0053 06 70		0052 6 70		0095 6 70		0090 6 70					
	75	0051 6 75		0053 6 75		0053 06 75											
	80	0051 6 80	100	0053 6 80	100	0053 06 80	100	0052 6 80	200	0095 6 80	50	0090 6 80	100				
	85	0051 6 85		0053 6 85		0053 06 85											
	90	0051 6 90		0053 6 90		0053 06 90											
	95					0053 06 95											
	100	0051 6 100	100	0053 6 100	50	0053 06 100	100	0052 6 100	100	0095 6 100	100	0090 6 100	100				
	110	0051 6 110		0053 6 110		0053 06 110											
	120	0051 6 120		0053 6 120		0053 06 120											