




ORSY



# Studs

## DIN 939

Steel 5.8 bright

Steel 8.8 bright

A2 rust proof

A4

Thread Ø d mm	M 6	M 8	M 10	M 12	M 14	M 16	M 20
b* mm	18	22	26	30	34	38	46
e mm	7.5	10	12	15	18	20	25

\* for length ≤ 125 mm

Thread Ø d	I mm	Steel 5.8 bright Art. No.	Pack Qty.	Steel 8.8 bright Art. No.	Pack Qty.	A2 <small>rust proof</small>	Pack Qty.	A4 <small>rust proof</small>	Pack Qty.
M 6	12			<b>0250 86 12</b>	250				
	16	<b>0250 6 15</b>	100	<b>0250 86 15</b>		<b>0272 6 16</b>			
	18	<b>0250 6 18</b>	200	<b>0250 86 18</b>					
	20	<b>0250 6 20</b>		<b>0250 86 20</b>		<b>0272 6 20</b>		<b>0277 6 20</b>	100
	25	<b>0250 6 25</b>	100	<b>0250 86 25</b>		<b>0272 6 25</b>			
	30	<b>0250 6 30</b>		<b>0250 86 30</b>		<b>0272 6 30</b>			
	35			<b>0250 86 35</b>		<b>0272 6 35</b>			
	40			<b>0250 86 40</b>					
	45			<b>0250 86 45</b>		<b>0272 6 45</b>			
	50			<b>0250 86 50</b>					
	55					<b>0272 6 55</b>		<b>0277 6 55</b>	100
	60	<b>0250 6 60</b>	100						
M 8	16	<b>0250 8 16</b>	1000	<b>0250 88 16</b>					
	20	<b>0250 8 20</b>		<b>0250 88 20</b>		<b>0272 8 20</b>		<b>0277 8 20</b>	
	25	<b>0250 8 25</b>		<b>0250 88 25</b>		<b>0272 8 25</b>		<b>0277 8 25</b>	
	30	<b>0250 8 30</b>		<b>0250 88 30</b>		<b>0272 8 30</b>		<b>0277 8 30</b>	
	35	<b>0250 8 35</b>		<b>0250 88 35</b>		<b>0272 8 35</b>		<b>0277 8 35</b>	
	40	<b>0250 8 40</b>		<b>0250 88 40</b>		<b>0272 8 40</b>		<b>0277 8 40</b>	
	45	<b>0250 8 45</b>		<b>0250 88 45</b>		<b>0272 8 45</b>		<b>0277 8 45</b>	
	50			<b>0250 88 50</b>		<b>0272 8 50</b>		<b>0277 8 50</b>	
	55	<b>0250 8 55</b>		<b>0250 88 55</b>		<b>0272 8 55</b>		<b>0277 8 55</b>	
	60	<b>0250 8 60</b>		<b>0250 88 60</b>		<b>0272 8 60</b>		<b>0277 8 60</b>	
	60			<b>0250 88 65</b>	200	<b>0272 8 65</b>			
	70	<b>0250 8 70</b>		<b>0250 88 70</b>		<b>0272 8 70</b>		<b>0277 8 70</b>	
	75			<b>0250 88 75</b>					
	80	<b>0250 8 80</b>		<b>0250 88 80</b>		<b>0272 8 80</b>		<b>0277 8 80</b>	
M 10	90					<b>0272 8 90</b>			
	100					<b>0272 8 100</b>			
	105	<b>0250 8 105</b>	100	<b>0250 88 105</b>	100				
	150			<b>0250 88 150</b>					
	180			<b>0250 88 180</b>	50				
	20	<b>0250 10 20</b>	500	<b>0250 810 20</b>	100				
	22					<b>0272 10 22</b>		<b>0277 10 22</b>	
	25	<b>0250 10 25</b>		<b>0250 810 25</b>		<b>0272 10 25</b>		<b>0277 10 25</b>	
	30	<b>0250 10 30</b>		<b>0250 810 30</b>		<b>0272 10 30</b>		<b>0277 10 30</b>	
	35	<b>0250 10 35</b>		<b>0250 810 35</b>		<b>0272 10 35</b>		<b>0277 10 35</b>	
	40	<b>0250 10 40</b>		<b>0250 810 40</b>		<b>0272 10 40</b>		<b>0277 10 40</b>	
	45	<b>0250 10 45</b>		<b>0250 810 45</b>		<b>0272 10 45</b>		<b>0277 10 45</b>	
	50	<b>0250 10 50</b>		<b>0250 810 50</b>		<b>0272 10 50</b>		<b>0277 10 50</b>	
	55	<b>0250 10 55</b>		<b>0250 810 55</b>				<b>0277 10 60</b>	
	60	<b>0250 10 60</b>		<b>0250 810 60</b>	50	<b>0272 10 60</b>			
	65	<b>0250 10 65</b>	50			<b>0272 10 65</b>			
	70	<b>0250 10 70</b>				<b>0272 10 70</b>		<b>0277 10 70</b>	
	80	<b>0250 10 80</b>	25	<b>0250 810 80</b>	25	<b>0272 10 80</b>		<b>0277 10 80</b>	
	85					<b>0272 10 85</b>			